

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2956	DATE	June 19 .2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In the charging device, the current limiter has improper inner structure combining element and infrastructure. Therefore, the lead may snap when the resin inside of the current limiter expands with raise in temperature. It causes sparks between the lead and the element, and as a result, it catches fire in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C22A	GC221	2000~2002	3,218
TOTAL			3,218