

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1847	DATE	June 22, 2012
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	A possible NON-conformity in the final stages of machining of crankshafts for the engine which may lead to failure in the incorrectly machined zone caused by thermal and dynamic stresses. In this case oil does not cover for connecting rod rotating. Engine seizure and consequent arrest of the vehicle, which could potentially cause an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F149	California	2011-2012	3
ABA-F142	458 Italia	2011-2012	3
		TOTAL	6