

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2962	DATE	June 27 2012
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>Due to the insufficient mounting of the battery wire harness to the chassis, there is a possibility to have irregular contacts between the battery wire harness and edges of chassis. It might cause a flaking off in the surface of battery wire harness and a result in the fatal short circuit with sparks while usage of machine.</p> <p>Result of this failure might cause an ignition to the hose of fuel line located close to the battery wire harness, and a fire of machine in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-CZ4YL	—	2006~2008	5
		TOTAL	5