

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1859	DATE	July 19, 2012
MANUFACTURE	Automobiles CITROEN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the components of the hydraulic ABS/ESP block in the engine compartment, wrong assembly of the fluid distribution piston in the hydraulic ABS/ESP block may occur the risk that they are not activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A5C5F02	CITROEN DS3	2012	77
		TOTAL	77