

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2 9 7 3	DATE	JULY-23-2012
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Yoshiaki Nagao		
SUMMARY OF DEFECT	As for fuel injection pump of engine, some deliivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EDM-S601A	KIORITZ SPEED SPRAYER SSV601 F	2012	3
EDM-S1008A	KIORITZ SPEED SPRAYER SSV1008 F	2012	8
EDM-S1075A	KIORITZ SPEED SPRAYER SSV1084 F S	2011~2012	16
		TOTAL	27