

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 9 8 8	DATE	July. 30. 2012
MANUFACTURER	TRANTECHS. CO., LTD		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-XZU412M	HINO DUTRO	2001	1
BKG-XZU414M		2008~2010	2
BJG-XKU414M		2008~2011	5
BJG-XKU424M		2009~2010	2
SJG-XKU710M		2011	2
SJG-FC9JKAH	HINO RANGER	2011	1
KK-FD1JKEA		2001~2002	2
KK-FD1JLEG		2002	1
KK-FD1JLEA		2003	1
BKG-FD7JLYA		2008~2011	2
BKG-FD7JPYA		2010	1
BKG-FD7JMYA		2010	1
BDG-FD8JPWG		2010	1
LKG-FE7JPAG		2011	2
BDG-GD8JLWG		2007	1
BKG-FR1EXYG	HINO PROFIA	2007	1
BDG-FR1EXYG		2010	2
BKG-FW1EXYG		2008	5
BDG-FW1EYYG		2007~2008	3
BDG-FW1EXYG		2008~2010	27
LKG-FW1EXBG		2011~2012	10
KL-FW1KXHG		2012	1
BKG-FN1AWXG		2009~2010	28
BKG-FN1AYYG		2010	10
LKG-FN1AYBG		2012	4
SKG-FEB50	FUSO CANTER	2011	1
BJG-NPR85AN	ELF	2009~2010	2
NFG-NPR82XAN		2008	1
BDG-LPR85AN	TITAN	2009	1
		T O T A L	121