

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3005	DATE	July 31,2012
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>In the front brake hose of the affected vehicles, since the installation of the electrical wiring harness for the ABS wheel speed sensor is inappropriate, the clearance between the subject wiring harness and the front brake hose may have been insufficient. If use continues under this condition, in the worst case scenario, the front brake hose could get damaged causing the brake fluid leakage resulting in the reduction of the braking force.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-U67V	MINICAB-MiEV	2011 TO 2012	1,518
		TOTAL	1,518