

VEHICLE SAFETY/POLLUTION REGCALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 9 9 2	DATE	July 30, 2012
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED 3034 Uenohara, Kamiichi, Atsugi, Kanagawa, JAPAN		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYJ77A	GIGA	2011	2 units
LKG-CYJ77AA		2010	2 units
PDG-CXY77V8J		2007	3 units
PDG-CYJ52W8A		2007	1 unit
PDG-CYJ77W8		2007	1 unit
PJ-CYJ52W6A		2006	2 units
ADG-FRR90L3	FORWARD	2007	1 unit
PA-FRD34L4		2004~2006	9 units
PDG-FRR34S2		2007~2010	17 units
PDG-FRR34T2		2007~2009	22 units
PKG-FRR90S1		2008	1 unit
PKG-FRR90S2		2008	2 units
PKG-FRR90T2		2007~2008	2 units
PKG-FSR34T2		2009	3 units
SKG-FRR90T2		2012	2 units
SKG-FSR90T2		2012	3 units
BDG-NKS85AN	ELF	2008	1 unit
BDG-NMR85AN		2008	1 unit
BDG-NMR85N		2007~2008	3 units
BDG-NMS85AN		2008~2009	5 units
BDG-NPR85AN		2007~2011	33 units
BJG-NJR85AN		2007~2008	3 units
BJG-NLR85AN		2010	1 unit
BLG-NPR85AN		2010	1 unit
BKG-LMR85AN		2008	1 unit
BKG-NHR85AN		2007~2008	2 units
BKG-NJR85AN		2007~2010	4 units
BKG-NLR85AN		2007~2011	25 units
BKG-NLR85N		2007~2009	6 units
BKG-NMR85AN		2007~2011	32 units
BKG-NPR85AN		2007~2011	20 units

NFG-NJR82AN		2008	3 units
NFG-NLR82AN		2007~2009	16 units
NFG-NMR82AN		2007~2008	7 units
NFG-NPR82XAN		2007~2009	24 units
PA-NPR81N		2005~2007	26 units
PB-NKR81AN		2006~2007	9 units
PDG-NPR75N		2009	1 unit
PKG-NPR75N		2008	1 unit
SDG-NKS85AN		2012	1 unit
SDG-NMS85AN		2012	1 unit
SFG-NMR82AN		2010	1 unit
SKG-NLR85AN		2011~2012	5 units
SKG-NMR85AN		2012	5 units
SKG-NNR85AN		2012	1 unit
SKG-NPR85AN		2011	1 unit
BDG-FR1EXYG	HINO PROFIA	2010	2 units
BDG-FW1EZYJ		2007~2008	2 units
BKG-FR1EXYG		2008	1 unit
BKG-FW1EXYG		2008	1 unit
KL-FR1KXHG		2002	1 unit
LKG-FW1EXBG		2011~2012	5 units
ADG-FD7JLWG	HINO RANGER	2007	1 unit
ADG-FD8JLWA		2006	1 unit
ADG-FD8JPWG		2006	1 unit
BDG-FD7JLWG		2008	2 units
BDG-FX7JLWA		2007	1 unit
BKG-FC7JGYA		2010~2011	4 units
BKG-FC7JHYA		2010	5 units
BKG-FC7JKYA		2008	1 unit
BKG-FD7JLYA		2008	1 unit
BKG-FD7JLYG		2008~2009	2 units
KK-FD1JKDA		2011	1 unit
BDG-XZU304M	HINO DUTRO	2009	1 unit
BDG-XZU308M		2007~2008	4 units
BDG-XZU344M		2007~2009	2 units
BDG-XZU414M		2006~2008	6 units
BDG-XZU508M		2007	3 units
BJG-XKU308M		2006~2007	8 units
BJG-XKU414M		2006~2008	3 units
BJG-XKU424M		2006~2008	2 units
BJG-XKU508M		2009~2010	5 units
BKG-XZU304M		2010	1 unit
BKG-XZU414M		2009~2010	2 units
BKG-XZU508M		2008~2011	9 units
BKG-XZU548M		2008	1 unit
PB-XZU306M		2006	1 unit

VF-XKU304E		2005	2 units	
VF-XKU414M		2006	4 units	
BDG-XZU304	DYNA OR TOYOAGE	2009	1 unit	
BDG-XZU304H		2007~2011	25 units	
BDG-XZU308		2009	4 units	
BDG-XZU368		2007~2011	4 units	
BDG-XZU414		2008~2010	4 units	
BDG-XZU508		2007~2010	16 units	
BDG-XZU568		2009~2010	2 units	
BJG-XKU308		2009	1 unit	
BJG-XKU308H		2007~2008	2 units	
BJG-XKU348		2008	1 unit	
BKG-XZU304H		2010	1 unit	
BKG-XZU508		2009~2011	5 units	
SKG-XZU605		2011	1 unit	
BDG-FS54JZ		FUSO	2007	12 units
LKG-FS54VZ			2010	1 unit
PDG-FK64F		FUSO FIGHTER	2007~2008	4 units
PDG-FK71F	2008~2009		4 units	
BJG-FE84B	FUSO CANTER	2008	1 unit	
BKG-FE70BS		2008	1 unit	
PA-FE70DB		2006	1 unit	
PA-FE82DEV		2006	1 unit	
PA-FE83DEY		2007	1 unit	
PDG-FB70B		2009	2 units	
PDG-FE70B		2007	4 units	
PDG-FE70BS		2008	2 units	
PDG-FE72D		2008	1 unit	
PDG-FE73D		2007~2008	3 units	
PDG-FE74BV		2007	2 units	
PDG-FE74DV		2007~2008	5 units	
PDG-FE82D		2009	3 units	
PDG-FE88DV		2007	1 unit	
ADG-CG4ZA		—	2010	1 unit
ADG-CG4ZE			2006	1 unit
ADG-CV4YL	2008		1 unit	
ADG-CV4YL改	2008		2 units	
KL-CD48L	2004		1 unit	
LKG-CG5ZE	2010		3 units	
PKG-CD4ZE	2009		1 unit	
PKG-CG4ZA	2008~2010		4 units	
PKG-CG4ZE	2010		1 unit	
PKG-CX4YA	2008		1 unit	
BDG-BPR85AN	CONDOR		2007	2 units
BDG-BPS85AN		2008	1 unit	
		TOTAL	534 units	