

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic/Import Vehicles)

CAMPAIGN No.	3030	DATE	September 28,2012
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD.		
DESCRIPTION OF DEFECT	<p>With regards to refuse compactor trucks, by reason of being inappropriate installation positions of rear lamps,positions of tail lamps and brake lamps do not comply safety standards for road trucking vehicle stipulating the outermost edge of lamps shall be installed within 400mm from the outermost edge of vehicles.</p> <p>As a remedy for the above, positions of rear lamps of all refuse compactor trucks will be changed by installing additional brackets</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-GC7JDYD	HINO RANGER	2010	1
LKG-FJ7JGA	HINO RANGER	2012	2
LKG-FJ7JEAA	HINO RANGER	2011	1
SKG-GC7JJAA	HINO RANGER	2011	1
SKG-FC9JDAA	HINO RANGER	2012	3
SKG-GC7JEAA	HINO RANGER	2012	1
TKG-FC9JEAA	HINO RANGER	2012	1
LKG-FJ7JJAA	HINO RANGER	2012	1
SDG-FC7JDAA	HINO RANGER	2012	1
SKG-FRR90S2	FORWARD	2011-2012	7
SKG-FRR90S1	FORWARD	2011	2
SKG-FSR90S2	FORWARD	2011	2
LKG-FK72FGZ1	FUSO FIGHTER	2011-2012	2
LKG-FK72FHZ1	FUSO FIGHTER	2012	1
SKG-MK38LBH	CONDOR	2011	1
LKG-PK39LEH	CONDOR	2012	2
SKG-MK38LCB	CONDOR	2012	1
SKG-LK38NEB	CONDOR	2012	1
SKG-MK38LBB	CONDOR	2012	1
		TOTAL	32