

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3023	DATE	SEP, 24, 2012
MANUFACTURER	Taiyo Automobile Industrial Place		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-XZU341M	HINO DUTRO	2006	1
KK-FD1JLEA	HINO RANGER	2007	1
ADG-FD8JLWA	HINO RANGER	2006	1
PA-FE72DEV	FUSO CANTER	2006	1
PA-FE82DEV	FUSO CANTER	2006	1
PA-FE82DEV	FUSO CANTER	2006	1
		TOTAL	6