

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3021	DATE	Aug. 30 2012
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On light-duty trucks and buses, the cushioning rubber which secures the fuel return hose to the engine is improper and the material released from the rubber (phthalate) makes the fuel hose soft and loose. The loose fuel hose may come off from the orifice to leak the fuel and, in the worst case, cause fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SGJ-FEA53	FUSO CANTER	2011~2011	3
SKG-FBA00		2010~2012	1,192
SKG-FBA20		2010~2012	2,848
SKG-FBA30		2010~2012	853
SKG-FBA60		2010~2012	1,533
SKG-FDA00		2011~2011	126
SKG-FDA20		2011~2011	64
SKG-FDA40		2011~2011	29
SKG-FEA20		2010~2012	543
SKG-FEA50		2010~2012	2,539
SKG-FEA70		2010~2011	82
SKG-FEA80		2011~2012	123
SKG-FEB20		2010~2012	187
SKG-FEB50		2010~2012	2,892
SKG-FEB70		2010~2012	536
SKG-FEB80		2011~2012	602
SKG-FEB90		2010~2012	1,010
SKG-FEC90		2010~2012	54
SKG-FGA20		2011~2011	34
SKG-FGB70		2011~2012	51
TKG-FBA20		2011~2012	80
TKG-FBA30		2010~2012	18
TKG-FBA60		2011~2012	41
TKG-FDA20		2012~2012	2
TKG-FDA40		2011~2011	2
TKG-FEA20		2011~2012	12
TKG-FEA50		2011~2012	47
TKG-FEA80		2011~2012	2
TKG-FEB20		2011~2012	3
TKG-FEB50		2011~2012	62
TKG-FEB80		2011~2012	15
TKG-FEB90		2011~2012	20
TKG-FGB70		2011~2012	3
TPG-FBA00		2011~2012	20
TQG-FEA53		2012~2012	2
SKG-BE640G	FUSO ROSA	2011~2012	225
SKG-BE640J		2011~2012	34
TPG-BE640G		2011~2012	10
TPG-BE640J		2011~2012	9
TOTAL			15,908