

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3016	DATE	31 Aug. 2012
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	Some of this vehicle's brake pipe may come into contact with power steering pipe, and then it has a hole by vibration. This may become a cause of oil leaking and the vehicle can not brake finally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA SF66D	MARUYAMA STEREO SPRAYER SSA-F616	2003 ~ 2004	255
MARUYAMA EDM-SF66D	MARUYAMA STEREO SPRAYER SSA-F616	2004 ~ 2011	373
		TOTAL	628