

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	3065	DATE	November 28, 2012
MANUFACTURER	NITTSU SHOJI CO., LTD.		
DESCRIPTION OF DEFECT	<p>Due to the improper crimping operation of the metal fitting device and the rubber hose used for the trailer's air braking system, the metal fitting's insertion point may damage the air hose and cause air leakage. Therefore, if continuously used at the present condition, brake would not activate if air leak occurs at the service-braking-system. Also, if air leak occurs at the emergency-parking-brake system, brake would activate permanently and brake rotor will over heat, and in the worst case, fire may occur.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NT13A018	–	2012	1
NT14A005	–	2011	2
NT14A006	–	2011	2
NT14A007	–	2012	1
NT15A005	–	2011	1
NT15A006	–	2012	1
NT17A013	–	2012	1
NT17A014	–	2012	1
NT18A017	–	2012	1
NT18A018	–	2012	2
NT1950	–	2011～2012	6
NT20A043	–	2011	1
NT20A044	–	2012	2
NT20A045	–	2012	1
NT20A046	–	2012	2
NT20H006	–	2012	2
NT20H007	–	2012	1
NT2105	–	2012	1
NT21A014	–	2012	1
NT2280	–	2011～2012	6
NT22A009	–	2011	1
NT22D004	–	2012	1
NT2340	–	2003～2012	4
NT23C011	–	2011	1
NT24A010	–	2012	1
NT24F003	–	2012	1
NT2527D	–	1990	1
NT25R002	–	2012	1
NT2699D	–	1975	2
NT36D010	–	2011	1
NT2809D	–	1988	1
NT2840	–	2011～2012	5
NT28D007	–	2011	1
NT28D008	–	2012	1
NT28F007	–	2011	2
NT2920	–	2011～2012	5
NT35D021	–	2011	1
NT3604K	–	1984	1
NT42F002	–	2011	2
NTP1703	–	1986～1990	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NTP1705	–	1987	1
NTP1804	–	1979	1
NTP1808	–	1986	1
NTP1810	–	1992~1995	5
NTP1810A	–	1993	1
NTP2041	–	1990	2
NTP2W9B	–	1977~1981	4
NT4017KA1	–	1993	1
NT3603KA1	–	1994	1
NT3612K	–	1994	1
NT1917A	–	1995	1
NT2224A	–	1995	1
NT1219V	–	1995	1
NT14P001	–	1998	1
NT19V006	–	2001	1
NT20A015	–	2005	1
NT21A004	–	2007	1
TOTAL			96