

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1883	DATE	Nov. 21. 2012
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	DURING LONG PERIODS OF RIDING AT SUSTAINED HIGH ENGINE RPM, VIBRATION WITHIN THE BRAKE FLUID RESERVOIR CAN CAUSE THE BRAKE FLUID TO FOAM. THIS COULD ALLOW AIR TO ENTER THE FRONT BRAKE SYSTEM WHICH COULD LEAD TO A LOSS OF FRONT BRAKING EFFICIENCY.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
K1200S	BMW K1200S	2007-2008	333
K1200R	BMW K1200R	2008	90
K1200R-S	BMW K1200R-S	2007	212
		TOTAL	635