

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	3 0 5 4	DATE	November,2,2012
MANUFACTURER	MITSUBISHI AGRICULTURAL MACHINERY CO.LTD.		
DESCRIPTION OF DEFECT	DUE TO IMPROPER ROUTING OF POWER STEERING HOSE, THE HOSE MAY BE DAMAGED BY VIBRATION AND OIL LEAKAGE OCCURS, AND IT POSSIBLY MAKES STEERING IMOPERATIVE.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-GT34B	GO261	2012	36
	GO261H		2
	GO281		20
	GO281H		2
	GO301		12
	GO301H		4
	GO321		7
	GO341		23
	GO341H		12
	GOK301		2
	GOK341		8
	TOTAL	128	