

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3045	DATE	October 25 ,2012
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some bearing seals were damaged on the manufacturing line for the universal joint journal bearing for light-duty truck propeller shafts. If the damaged bearing seals continue to be used, grease may flow out of the bearing, causing poor lubrication, and in the worst case, the bearing may seize.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-NHR85A	ELF	2011	3
SKG-LHR85A SKG-LHR85AN	TITAN	2011	16
TOTAL			19