

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-1940	DATE	July 04, 2013
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	<ol style="list-style-type: none"> 1. Risk of fuel leakage from one of two vapor discharge valves on a fuel tank by inner pressure of a fuel tank while fuel tank is full, and depend on motion of the vehicle, due to improper installation position of the valve. 2. Risk of engine stalling or unstartable of engine, because improper length of wire between a fuel pump and vehicle side then it makes disconnection. 3. (Product improvement) To reduce risk of fuel leakage when a front impact, a fuel pipe protector is installed only for the vehicles which have no fuel pipe protector in an engine compartment. 4. Risk of falling off of a fuel pipe protector in an engine compartment, due to improper design and metal fatigue by sympathetic vibration of engine. 		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWK4M ABA-KWK4MG	「KANGOO」 「KANGOO BE BOP」	2009-2012	5786
		TOTAL	5786