

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2152	DATE	Feb. 20 2015
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation)		
DESCRIPTION OF DEFECT	On some articulated buses, there may be a gap between the base plate for roof-mounted fan and the roof because of improper production process of the base plate. This gap allows ingress of water between the roof and the base plate. If the bus continues to be used in this condition, the base plate will corrode and, in the worst case, the roof-mounted fan will fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2012～2012	2
TOTAL			2