

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2137	DATE	Feb. 6, 2015
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	SAFETY RECALL: Certain 2014 Model Year EcoSport Vehicles – Main Harness RCM Connector Wiring Certain right hand drive EcoSport vehicles fitted with curtain airbag built in Chennai India between 4 April 2013 and 26 September 2014. On affected vehicles the curtain airbag, seatbelt pre-tensioner and side impact sensor circuits are incorrectly orientated between the right hand side and left hand side in the main wiring harness RCM connector. Dealers are required to correct the wiring orientation of the main harness RCM connector.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA – MAJUEJ	EcoSport	2014	331 unit
TOTAL			331 units