

**VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN**

**Domestic Vehicles**

<b>CAMPAIGN No.</b>	3559	<b>DATE</b>	April 22, 2015
<b>MANUFACTURER</b>	SUZUKI MOTOR CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	<p>Grease applied at the contact point of the ignition switch may carbonize with heat repeatedly generated from arc discharge when the travelling side leaves from the fixed side at the contact point, due to the very grease being improper for the contact point. If the vehicle is used continuously as it is, the grease can make smoke due to heat from unexpected conduction of the switch with grease deterioration of insulation performance and abrasion powder accumulated around the contact point. In the worst case a fire might be induced.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
GF-HA12S	ALTO	1998～2000	96,497
GD-HA12V		1998～2000	74,609
GF-HA22S		1998～2001	16,644
LA-HA23S		2000～2004	118,898
TA-HA23S		2001～2004	176
UA-HA23S		2002～2004	1,808
ABA-HA23S		2004	10,730
CBA-HA23S		2004	267

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LE-HA23V	ALTO	2000～2004	98,999
UE-HA23V		2002～2004	817
GBD-HA23V		2004	256
GF-HN11S	KEI	1998～2001	78,041
TA-HN12S		2001	17,281
GF-HN21S		1998～2001	26,464
LA-HN22S		2001～2002	10,109
UA-HN22S		2002～2004	19,648
TA-HN22S		2001～2007	71,475
ABA-HN22S		2007～2009	9,709
CBA-HN22S		2004～2009	75,285
GF-MC11S	WAGON R	1998～2000	113,511
TA-MC12S		2000～2001	30,163
GF-MC21S		1998～2000	299,396
LA-MC22S		2000～2003	204,568
UA-MC22S		2002～2003	146,417
TA-MC22S		2000～2003	97,420

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-EC22S	TWIN	2002～2004	6,607
CBA-EC22S		2004～2005	2,975
CAA-EC22S		2004～2005	16
UA-EC22Skai		2003	274
GH-HT51S	SWIFT	2000～2001	13,834
LA-HT51S		2001～2005	43,230
UA-HT51S		2003～2005	42,098
TA-HT81S		2003～2005	4,704
GF-HB12S	CAROL	1998～2000	7,277
GF-HB22S		1998～2001	542
LA-HB23S		2000～2004	11,272
UA-HB23S		2002～2004	318
TA-HB23S		2001～2003	35
ABA-HB23S		2004	950
CBA-HB23S		2004	43
GF-HP11S	LAPUTA	1999～2001	4,190
TA-HP12S		2001	1,407

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GF-HP21S	LAPUTA	1999～2001	1,488
LA-HP22S		2001～2002	489
UA-HP22S		2002～2004	1,462
TA-HP22S		2001～2005	5,114
CBA-HP22S		2004～2005	1,720
GF-MD11S	AZ-WAGON	1998～2000	3,312
TA-MD12S		2000～2001	1,303
GF-MD21S		1998～2000	18,987
LA-MD22S		2000～2003	14,300
UA-MD22S		2002～2003	14,981
TA-MD22S		2000～2003	4,935
LA-HR51S		2001～2003	16,687
LA-HR52S	CRUZE	2003～2005	3,378
ABA-HR52S		2005～2008	2,187
UA-HR52S		2003～2005	12,762
DBA-HR52S		2005～2008	6,504
LA-HR81S		2001～2003	1,815

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LA-HR82S	CRUZE	2003~2005	921
ABA-HR82S		2005	367
UA-HR82S		2003~2005	903
CBA-HR82S		2005	333
	TOTAL		1,872,903