

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3549	DATE	Apr.13 2015
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For the parking brake of wheel cranes, found that surface of the axle where the bracket of the brake chamber is fitted might have an improper finish, therefore, it might have fitting bolts tighten insufficiently. In case that you continue to use the vehicle with the condition, the chamber could be off from the right position due to vibration while driving, then you might have failure of the parking brake at worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
UDS－KRC011	KR - 25H	2013～2014	850	
UDS－KRC015	KRM - 35H	2014	4	
TOTAL			854	