VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2157	DATE	2015/3/10	
MANUFACTURE	Daimler AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)			
DESCRIPTION OF DEFECT	series 212) and CLS-Class (r correct seating of the engine installation. If the engine complanned, the seal might temporase, the engine compartment in unfavorable circumstances into the gap between the engine compartment seal is departition wall, it cannot be rule comes in contact with parts or	There was a visual design change on the engine compartment seal on E-Class (model series 212) and CLS-Class (model series 218) vehicles. The visual feedback of the correct seating of the engine compartment seal was limited as a result during the installation. If the engine compartment seal was not fastened to the partition wall as planned, the seal might temporarily adhere to the engine hood when it is opened. In this case, the engine compartment seal might partially detach from the partition wall. In unfavorable circumstances, a partially detached engine compartment seal may fall into the gap between the engine and the partition wall. If a long enough part of the engine compartment seal is detached and falls into the gap between the engine and the partition wall, it cannot be ruled out that the loose end of the engine compartment seal comes in contact with parts of the exhaust system, in particular the catalytic converter. If the catalytic converter is hot enough, a potential risk of fire cannot be ruled out.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
RBA-212036C	E250	2014	5,301
		2015	626
DBA-212047C	E250CGI	2013	1,183
	E300	2013	395
RBA-212055C		2014	685
		2015	79
RBA-212080C		2013	70
	E300 4MATIC	2014	346
		2015	54
		2013	350
RBA-212059C	E350	2014	1,027
		2015	2
DAA-212095C	E400 HYBRID	2014	506
		2015	37
CBA-212073	E550	2013	31
		2014	114
DBA-212073		2015	7

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-212074	E63	2013	28
		2014	128
		2015	1
CBA-212075	E63S	2014	63
		2015	2
CBA-212076	E63S 4MATIC	2014	93
		2015	3
CBA-212092	E63 4MATIC	2014	73
RBA-212236C	E250	2014	2,371
	STATIONWAGON	2015	302
DBA-212247C	E250 CGI STATIONWAGON	2013	618
	_	2013	65
RBA-212255C	E300 STATIONWAGON	2014	301
	STATIONWAGON	2015	27
	E300 4MATIC STATIONWAGON	2013	63
RBA-212280C		2014	277
		2015	42
DDA 212250C	E350 STATIONWAGON	2013	90
RBA-212259C		2014	404
CBA-212273		2013	11
GBA-212273	E550 STATIONWAGON	2014	61
DBA-212273	STATIONWAGON	2015	7
CBA-212274	E63 STATIONWAGON	2013	3
CBA-212292	E63 4MATIC	2014	41
	STATIONWAGON	2015	2
CBA-212276	E63S 4MATIC STATIONWAGON	2014	49

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-218359C	IVAIVIE	2013	86
		2014	255
RBA-218359	CLS350	2013	419
		2014	714
CBA-218373	CLS550	2013	144
		2014	189
DBA-218373		2015	97
CBA-218991	CLS550 4MATIC	2013	97
		2014	88
DBA-218991		2015	25
	CLS63	2013	65
CBA-218374		2014	72
CDA 210275	CLS63S	2014	23
CBA-218375		2015	18
CDA 210274	CLS63S 4MATIC	2014	25
CBA-218376		2015	26
CDA 219202	CLS63 4MATIC	2014	24
CBA-218392		2015	1
CDA 210076	CLS63S 4MATIC SB	2014	17
CBA-218976		2015	14
CBA-218992	CLS63 4MATIC SB	2014	16
DDA 0400500		2013	109
RBA-218959C	CLS350 SHOOTING BRAKE	2014	79
RBA-218959		2013	739
		2014	237
ABA-218974	CLS63 SHOOTING BRAKE	2013	137
		TOTAL	19,654