

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2155	Date	March. 04, 2015
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>A concern has been identified within the assembly process where certain underbody brake pipe unions may not be to the correct torque specification.</p> <p>Low torque at the underbody brake pipe unions can lead to a loss of mechanical integrity of the braking system. This can result in extended brake pedal travel combined with reduced braking performance in the corresponding brake circuit. The instrument cluster may display the warning message 'Fluid Level Low', along with the Brake Warning lamp being illuminated. In the event of both braking circuits losing integrity at the same time, complete loss of service brakes will occur, potentially causing a vehicle crash.</p> <p>It is also possible that sufficient loss of brake fluid will deplete the brake pressure in the system such that the brake pressure switch, required as part of the vehicle start authorisation process, may not be activated so preventing initial vehicle start-up.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-J12PB	「Jaguar XJ Lux.」	2014-2015	12
CBA-J128B	「Jaguar XJ Prem. Lux.」	2014-2015	11
CBA-J12MA	「Jaguar XJR」	2014-2015	7
CBA-J24MA	「Jaguar XJ Supersport LWB」	2014-2015	5
		Total	35