

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2185	DATE	May 22, 2015
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	<p>There is a possibility that the electric wire harness for the rear left radiator fan in the engine compartment is touching a heat guide plate made of carbon fibre on the affected vehicles. If the wire harness is touching, relative movements can cause visible damage to the wire harness or the insulation on individual lines of the wire harness.</p> <p>Progressive damage to the wire harness can cause the radiator fan to stop working and an electric shunt circuit to the low-resistance heat guide plate cannot be ruled out.</p> <p>This electric shunt circuit can cause the vehicle to go on fire even a long time after stopping the vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	918Spyder	2015	28
		TOTAL	28