## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2178	DATE	May 22 <sup>nd</sup> 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the unclear stamp (of wheel size) on the alloy wheels, their compliance with the safety regulation cannot be confirmed. The stamp shall be displayed clearly on the product, of which the conformation to the technical standards defined in the "Technical standards of light alloy disc wheel" is assured.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-XG20	BMW 523i	2013 - 2014	569
DBA-XL20	BMW 523i Touring	2013 - 2014	247
LDA-FW20	BMW 523d	2013 - 2014	537
LDA-MX20	BMW 523d Touring	2013 - 2014	399
DBA-XG28	BMW 528i	2013 - 2014	226
DBA-XL28	BMW 528i Touring	2013 - 2014	54
		TOTAL	2,032