

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2179	DATE	Mar 20, 2015
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	HarleyDavidson has learned that the hydraulic clutch system equipped with master cylinder part numbers 36700056 and 36700049 on certain model year 2014 and 2015 Touring model motorcycles may exhibit a condition in which it may lose the ability to generate enough lift to disengage the clutch after being parked for an extended period.  If this condition remains undetected it could lead to a loss of control of the vehicle when started in gear or first shifted into gear after being parked for an extended period.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-FLHM	STREET GLIDE	2014	61
EBL-FLHL	ULTRA LIMITED	2014-2015	26
EBL-FLHL	ELECTRA GLIDE URTRA CLASSIC LOW	2015	58
EBL-FLHL	ULTRA LIMITED LOW	2015	119
EBL-FLHM	STREET GLIDE SPECIAL	2015	411
EBL-FLHL	ELECTRA GLIDE URTRA CLASSIC	2014-2015	20
EBL-FLHM	ROAD GLIDE SPECIAL	2015	170
PG8	CVO™ ROAD KING	2014	23
PXN	CVO™ STREET GLIDE	2015	55
		TOTAL	943