

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3593	DATE	Jun. 18 2015
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks, the release bolt assemblies to release the spring brakes are not installed to the brake chambers. If a failure occurs in the air system of a spring brake and the spring brake is applied, there is no way to release the spring brake.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-FU60VY	「FUSO SUPER GREAT」	2014～2015	16
QPG-FU60VZ		2015～2015	8
		TOTAL	24