VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2195	DATE	June 11 th , 2015
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	The electric fuel pump may be contaminated due to inappropriate manufacturing. Thus, when keep driving under such condition, the contamination could be pressed into the impeller of the pump, and the pump may stop operation. In the worst case, the engine may stall and fail to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3R20	B3 Biturbo	2012	19
	B3 Biturbo Touring	2012	5
		TOTAL	24