## CHILD RESTRAINT SYSTEM SAFETY RECALL CAMPAING IN JAPAN

Domestic Import Items

CAMPAING No.	装10	DATE	8-Jun- 2015			
MANUFACTURER	CARMATE MFG. CO., LTD.					
DESCRIPTION OF DEFECT	In relevant Child Restraint Seat listed below, Due to the inadequateness for the end treatment of metal pate, Buckle belt might be damaged by the friction between the buckle belt and the metal plate which is used in the buckle assembly. This may come off the case that the damage of shoulder harness get worse and these might be a danger that these Child Restraint Seat can't hold occupant sufficiently due to the fracture of relevant belt in the worst case.					

COMMERCIAL NAME	ТҮРЕ	CLASSIFICATION	MODEL YEAR RECALLED		NUMBER OF ITEMS
Ailebebe Kurutto3i (Premium/	E43-44R-04 0012	Groups 0+/I	A serial number L40F800001~ L40F807720		7, 273pcs.
Grance)			(2014. 11. 4	2015. 1. 5)	
BF840 BF841 BF842 BF843 BF844 BF850 BF851 BF852 BF853 BF800E BF801E BF802E BF803E			(2015. 1. 6	2015. 5. 13)	3, 455pcs.
				TOTAL	10,728pcs.