

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-2187	DATE	June 4, 2015
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	<p>(1) The structure of the sign board located at the center area between the upper front lights on the high roof model heavy duty trucks may not be in conformance with Article 42 of the Japan Safety Regulations.</p> <p>(2) Regarding the engine controlling unit on heavy duty trucks, the engine control program may be inappropriate and in conditions where the exhaust gas temperature is low, urea may not be properly emitted and the nitrogen oxide (NOx) emission value may exceed the value required under Article 31 of the Japan Safety Regulations.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
QKG-H2TDA1	FH	2014-2015	51	(1) 51 (2) 31
QKG-H2TEA1		2014-2015	54	(1) 54 (2) 34
-H2TEA1-		2015-2015	4	(1) 4 (2) 1
Unspecified		2014-2015	49	(1) 10 (2) 39
		TOTAL	158	(1) 119 (2) 105