

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

Campaign No.	Gai-2184	Date	July /17 ,2015
Manufacturer	BOMAG GmbH (Japanese importer: KOBELCO CONSTRUCTION MACHINERY CO., LTD.)		
Description of Defect	With the vibration roller, its original fixation of the wire harness in the area of the articulation joint with rubber protection mat and hard tie rap was not appropriate so that the movability of the wire harness may be impaired at the time of articulated operation of the vehicle. As a result this may give unreasonable force on the wire harness in the area of the articulation joint. In case of continuous operation under this condition, the wire harness may be damaged, which in the worst case may lead to such troubles as engine stop failure and brake malfunction during travel operation.		

Type	Commercial name	Model year recalled	Number of Vehicles
—	BW131ACW-2	2006 - 2007	215
	BW131ACW-3	2007 - 2012	315
	BW131AD-2	2006 - 2007	20
	BW131AD-3	2007 - 2011	23
Total			573