VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2214	DATE	August,28, 2015
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	With regards to the driver's side airbag, Due to the production process problems in a Takata factory, some driver air bags for Ferrari vehicles could have been manufactured with the leather cover not properly glued and/or with the bag folding not complying with design specifications. The consequence of these non-compliances could be the deployment of the bag with a behavior different from the normal pattern.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F142	458Italia / 458 Spider	2015	39
ABA-F142VS	458Speciale	2015	61
ABA-F152	F12 berlinetta	2015	8
ABA-F142ADL	458Speciale A	2015	10
ABA-F149DD	California T	2015	26
ABA-F151	FF	2015	8
AAA-F150	La Ferrari	2015	4
		TOTAL	156