VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3622	DATE	August 27,2015	
MANUFACTURER	MITSUBISHI MOTORS CORPORATION			
DESCRIPTION OF DEFECT	In the parking brake cable for the vehicle with turbo charger, the right side parking brake cable may interfere with the fuel tank due to inappropriate installation of the cable. As a result, if use continues under the condition, the coating on the fuel tank would come off causing the tank to be rusted, and in the worst case scenario, fuel could leak from the hole created by the rust.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-CZ4A	「LANCER EVOLUTION」	2014	382
CBA-CX4A	「GALANT」	2014	53
CBA-CY4A	「GALAN1」	2014	51
		TOTAL	486