## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-2245	DATE	October 21, 2015	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	Due to poor manufacturing of fuel pump, plating finish for internal parts would be peeled off and remained as foreign object in the component; which, might be caught in impeller and fuel pump stops working. In the worst case, engine stalls during driving and impossible to restart.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AUCHH	「VW Golf GTI / 162kW」	MY2014	131
ABA-AUCJXF	「VW Golf R 2.0/206kW」	MY2014	314
DBA-AUCHP	「VW Golf variant 1.4/103kW」	MY2014	247
DBA-AUCJZ	「VW Golf 1.2/77kW/」	MY2014	317
DBA-AUCJZ	「VW Golf variant 1.2/77kW」	MY2014	163
DBA-AUCPT	「VW Golf 1.4/103kW」	MY2014	308
		Total	1,480