

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2242	DATE	October. 1. 2015
MANUFACTURER	HONDA AUTOMOBILE (THAILAND) CO., LTD.		
DESCRIPTION OF DEFECT	For the front passenger's airbag, its inflator may be filled with gas generating propellant that has become less dense than usual due to inadequacies in the gas generating propellant molding process or in the prevention of moisture absorption after molding. Such gas generating propellant can, if and when the airbag inflates, cause abnormal rise in internal pressure of the inflator by which the container of inflator could be broken and scattered about, causing fire or injury to the passenger.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GD6	「FIT ARIA」	2002	2
LA-GD8			3
LA-GD9			1
		TOTAL	6