VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

			Domestic Vehicles	
CAMPAIGN No.	3678	DATE	November 26 , 2015	
MANUFACTURER	VANTECHSALES Inc.			
DESCRIPTION OF DEFECT	Because the design of the door to the residence space (entrance door) locking mechanism is inappropriate, in case the resin part, in the latch, gets force of external			
	power, when the door close. Therefore the part will be damage	aed if keep usina. it mi	ght not be able to open the door.	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABF-TRY230	TOYOACE	2014	1
ABF-TRY230 KAI	CAMROAD	2013-2015	49
QDF-KDY231	DYNA	2014-2015	2
QDF-KDY231	、 TOYOACE	2014-2015	3
QDF-KDY231 KAI	CAMROAD	2013-2015	256
LDF - KDY231 KAI	CAMROAD	2013-2014	2
LDF - KDY281 KAI	CAMROAD	2013-2015	272
TKG-NJS85AN KAI	ELF	2013-2015	17
TRG-NJS85AN KAI	ELF	2015	1
		TOTAL	603