## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN No.	Gai-2227	DATE	November 19 <sup>th</sup> , 2015	
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	The component part of the retractor on the front right seat belt might be inappropriately manufactured, so that the retractor might be locked at low outside temperature. In such case, the passenger cannot pull out and fasten the seat belt.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-2A15	BMW 218i Active Tourer	2014	1,043
LDA-2E20	BMW 218d Gran Tourer	2015	40
DBA-2D20	BMW 220i Gran Tourer	2015	1
DBA-2A20	BMW 225i xDrive Active Tourer	2014	6
		TOTAL	1,090