VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

| CAMPAIGN No. | 3668 | DATE | November 4, 2015 | | |
|----------------|---|------|------------------|--|--|
| MANUFACTURER | KOBELCO CRANES CO.,LTD | | | | |
| DESCRIPTION OF | Regarding the air-conditioner which is equipped on the wheel | | | | |
| DEFECT | crane RK250-8, the shape of the mounting bracket for the | | | | |
| | compressor is improper. So a part of the mounting bracket would | | | | |
| | be received concentrated load by vibrating of the compressor. And | | | | |
| | crack(s) would occur. | | | | |
| | If in case it keeps using it with the crack, the crack would be expanded, and the mounting bracket would be broken. Then it | | | | |
| | | | | | |
| | might be a cause of dropping down of the compressor. | | | | |

| ТҮРЕ | COMMERCIAL | MODEL YEAR | | NUMBER OF |
|----------|------------|------------|------|-----------|
| | NAME | RECALLED | | VEHICLE |
| UDS-EE04 | RK250-8 | 2013-2015 | | 70 units |
| | | Т | OTAL | 70 |