

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2285	DATE	December 24 th , 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The ISOFIX child seat fastening bracket on the left-hand rear seat may have been inappropriately mounted. This may prevent the ISOFIX child seat being fitted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-XG20	BMW 523i	2015	31
LDA-FW20	BMW 523d	2015	88
DBA-XG28	BMW 528i	2015	46
DBA-FR35	BMW 535i	2015	7
CBA-KN44	BMW 550i	2015	1
ABA-FV44M	BMW M5	2015	2
		TOTAL	175