

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3966	DATE	January 20 ,2017
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	A damaged sealing cap and an O-ring have been installed in some of the disk caliper of braking system,Therefore,a sliding portion will be stuck because of rust generation caused by rain water and other intrusion into a caliper.And on the worst case,there is a possibility that braking force will be reduced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
AR139B	—	2007	13
PFW24101	—	2016	8
PFW24102	—	2013~2015	43
PFW24112	—	2014	4
PFW342NV	—	2015	2
VFB24101	—	2016	2
VFB24102	—	2007	8
VPD242AB	—	2014	1
VPD242AC	—	2015	1
		TOTAL	82