

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 9 7 0	DATE	J a n . 1 7 . 2 0 1 7
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate attachment of the brake cable to the rear wheel brake of the vehicle equipped with a parking stand (which is to maintain the body of the vehicle with the rear wheel touching the ground), a play of the brake lever may become greater at an early stage.</p> <p>Because of that, the parking stand may not be able to be lowered unless the brake lever is tightly gripped and the brake cable can be excessively pulled. In the worst case scenario, the said cable may be cut causing the rear wheel brake to become ineffective.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B H - U A 0 6 J	GEAR BX50S	2 0 1 4 ~ 2 0 1 5	1 , 4 4 0
J B H - U A 0 7 J		2 0 1 5 ~ 2 0 1 6	1 , 4 9 6
		TOTAL	2 , 9 3 6