VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	398	1	DATE	January 30, 2017
MANUFACTURER	ISEKI & CO., LTD.			
DESCRIPTION OF DEFECT	A silencer of the agricultural tractor may be cracked by heat of the exhaust and vibration of the engine because the material strength of the silencer is insufficient for the heat exhaustion. Therefore, the exhaust gas leak from the crack, and the use in the condition may lead to progresses a crack, and the silencer is damaged, and in the worst case scenario, around the silencer may melt.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
KDN-T196F	「NT50FF」	2013-2014		318
KDN-T197F	「NTA55FF」	2013-2014		629
	「NT55FF」	2013-2014		402
			TOTAL	1, 349