

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2436	Date	February 14, 2017
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>A concern has been identified with brake hoses installed on 2006 to 2012 Model Year (MY) Range Rover vehicles. Customers may experience a loss of brake fluid as a result of rupturing of one or both of the front brake jump (flexi) hoses. This may result in the loss of the front brake circuit. The vehicle braking system is a dual circuit system, one system operates the front braking circuit and the other system operates the rear braking circuit.</p> <p>A vehicle exhibiting sudden loss of brake fluid will illuminate a red warning triangle on the instrument cluster whilst displaying the words 'check brake fluid'. The driver should seek qualified assistance. Loss of fluid will also result in failure of the front braking circuit. Braking capability will be retained by the rear brake circuit, pedal feel will be degraded and pedal travel extended. Stopping distances will increase.</p> <p>There have been no reported accidents, injuries or fires as a result of this concern.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LM42S	「Range Rover」	2006-2012	392
ABA-LM44			680
ABA-LM5N			285
ABA-LM5S			113
Total			1,470