

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2448	DATE	2017/2/23
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain E-Class right hand drive vehicles (213 platform) the wiring harness to the front wiper motor may not have been routed according to specification in the area of the wiper struts. In this case, on right hand drive vehicles, the wiper struts could potentially damage the wiring harness while the wiper is in operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-213004C	E220d	2017	702
RBA-213042C	E220	2017	3,063
DBA-213043C	E200 4MATIC	2017	153
RBA-213045C	E250	2017	563
RBA-213071	E400 4MATIC	2017	135
		<b>TOTAL</b>	<b>4,616</b>