

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	3973	DATE	February 3, 2017
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD		
DESCRIPTION OF DEFECT	<p>With regard to the hydraulic gear pump of the wheel crane, bolts which are component of the hydraulic gear pump have not had enough strength. Therefore bolts can be cracked due to vibration during operation such as driving.</p> <p>In case the machine is used continuously without repair, crack can cause break of bolts. In the worst case, the machine would not be able to be operated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-EE02	RK250-7	2008-2013	274 units
CM03	MK650	2014-2016	4 units
CM03L	MK650	2014-2016	11 units
TOTAL			289 units