

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4002	DATE	Feb.17.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger air bag inflator of the subject vehicles, due to improper operation at the vehicle assembly plant, there is a possibility that the parts applied to the vehicles for foreign countries may have been installed in some vehicles. In this condition, the airbag may not inflate properly during deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE151N	[COROLLA RUMION]	2007	3
DBA-ZRE152N			1
		2010	1
		TOTAL	5