VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4023	DATE	Mar.30.2017
MANUFACTURER	ТОУОТА		
DESCRIPTION OF DEFECT	The subject vehicles are equipped with a Vehicle Stability Control System (VSC). Due to improper brake control programming, the vehicle velocity may have been calculated improperly during wheel slip. If this occurs, the brake may not be performed as designed, causing an increase of the braking distance in the condition of wheel slip, such as when the vehicle is driven on snowy roads.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-TRH219W	[HIACE]	2016-2017	1,639
CBA-TRH219W			
"kai"(modified)			
CBA-TRH229W			586
CBA-TRH229W			
"kai"(modified)			
CBF-TRH228B	[HIACE]		479
CBF-TRH228B	[REGIUS ACE]		
"kai"(modified)			
		TOTAL	2,704