

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2457	DATE	Apr 6, 2017
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	Certain 2016 model year Cadillac CTS vehicles equipped with AWD (RPO F46), Stop/Start System (RPO KL9), and a 2.0L engine (RPO LTG), may have an engine ground cable (EGC) that could come in contact with the passenger side half-shaft assembly, which may cause the EGC to wear through the insulation and the cable diameter may reduce over time. If this occurs, a noise near the front passenger's side may be heard while the vehicle is in motion. If the insulation on the EGC is worn through to the bare cable, arcing may occur between the EGC and half-shaft at engine start. If the EGC is severed while the vehicle is in motion, and the driver brakes to a stop and the vehicle enters stop/start mode, the engine will shut off and various driver information center (DIC) messages will display. The vehicle will not be able to re-start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「ABA-A1LL」	「CTS」	2016	53
		TOTAL	53