

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	Gai-2474	DATE	April 24 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fault involves the ventilation line on the fuel evaporative emission control system, which transfers fuel vapor to the engine. Due to inappropriate routing, the ventilation line might rub against the power supply cable. Thus, the ventilation line might be damaged and fuel vapor might leak from the damaged part, causing the risk of a thermal incident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-WY20	BMW i3	2013 - 2016	1,458
		TOTAL	1,458