

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2458	DATE	Apr 6, 2017
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	Zafira-B – MY 2016 - Only RHD vehicles with manual Air Conditioning (RPO Code C60), may have a heater fan motor resistor might overheat. Malfunction of the resistor, which is designed to protect the blower motor system. In addition, water may enter the heater fan motor resulting in corrosion and heater fan motor locking. A locked/seized heater fan motor may cause a heater fan motor resistor to overheat/melt inside the HVAC System housing and in the worst case could lead to a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「GH-AH05Z22」	「ZAFIRA」	2006	131
		TOTAL	131